

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,868,080 B1
DATED : March 15, 2005
INVENTOR(S) : Umansky et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2,

Line 56, replace "DSO" with -- DS0 --.

Column 3,

Line 13, replace "VoIP call I" with -- VoIP call 1 --.

Lines 59 and 60, replace "20. The quality" with -- 20. The quality --.

Column 4,

Line 5, replace "interface couples" with -- interface 30 couples --.

Lines 29 and 41, replace "DSO" with -- DS0 --.

Line 31, (both occurrence) replace "DSO" with -- DS0 --.

Column 5,

Lines 34 and 52, replace "DSO" with -- DS0 --.

Column 6,

Lines 50, 51 and 61, replace "DSO" with -- DS0 --.

Column 8,

Lines 15, 16, 17, 19, 20 and 21, replace "DSO" with -- DS0 --.

Column 9,

Line 23, replace "call is are being" with -- call are being --.

Lines 53, 54, 57, 59 and 60, replace "DSO" with -- DS0 --.

Column 10,

Line 19, replace "IDSN" with -- ISDN --.

Line 61, replace "DSO" with -- DS0 --.

Column 11,

Lines 58, 60, 63, 64, 65 and 66, replace "DSO" with -- DS0 --.

Column 12,

Line 43, replace "call to the fallback." with -- call to the fallback call. --.

Line 49, replace "establishment of new VoIP" with -- establishment of a new VoIP --.

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,868,080 B1
DATED : March 15, 2005
INVENTOR(S) : Umansky et al.

Page 2 of 2


It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 14,

Line 2, replace "call has degrade below" with -- call has degraded below --.

Signed and Sealed this

Twenty-first Day of March, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office